






X-5M

Assembly instructions

PARTS

① X 1	A.M6*25 X 4
② X 1	B.M6*20 X 4
③ X 1	C.M6*40 X 4
④ X 1	D.X 4
⑤ X 1	E.X 1
⑥ X 1	F.X 5
⑦ X 1	G.X 2    H.X 2



**NOTICE:**  
EVERY 6 MONTHS, PLEASE MAKE SURE ALL BOLTS, SCREWS AND KNOBS ARE FULLY TIGHTENED TO ENSURE STABILITY.